

To get the CFX file to work in uAnalyze:

- 1 ) Export the raw melt data (temperature and fluor values) as a csv
- 2) Format raw .csv as a LC96 file by taking that .csv and re-saving it as a tab delimited .txt file
- 3) Make sure to select LC96 as the file import option in the uAnalyze interface

The data should now import and display for use in uAnalyze